GILBARCO
VEEDER-ROOT

Gilbarco POS EMV Roadmap

January, 2017

EMV Acceptance & Deadlines

EMV = Europay, MasterCard & Visa

Prior to the EMV counterfeit liability shift dates, financial institutions absorbed liability/fraud charges incurred by counterfeit cards. Merchants not accepting EMV by the dates listed below, will be issued chargebacks from counterfeit transactions. Meaning, merchants absorb the liability/fraud charges instead of the financial institutions. EMV is more secure than magnetic stripe.

New POS PINPads & Fuel Dispensers are equipped to accept EMV Cards

EMV Compliance Dates

Inside: October 1, 2015

Fuel Island: October 1, 2020

Gilbarco Passport EMV Roadmap

1. Servers PX52 or PX60

2. Broadband Communication (DSL, Cable, T1, etc.) with EMV software upgrade

3. Installation and use of a PCI Compliant firewall with EMV software upgrade from a CITGO authorized firewall provider as listed on MarketNet

4. EMV Capable PINPad (Ingenico iSC250 or Verifone Mx915) New locations and PIN pad replacements must use Verifone Mx915 PIN Pads

5. Upgrade to indoor EMV software (version 11.01 or CITGO version 007). (Software available May 20, 2016) EMV Indemnification concluded November 1, 2016

6. Locations using older versions of Gilbarco Passport software such as versions 8 or 10 (CITGO software versions 001 or 005) will be deactivated on June 30, 2017

7. Upgrade Fuel Islands to accept EMV by October 1, 2020

Gilbarco POS INDOOR EMV Roadmap

Passport PX52 Server and all other Passport Servers using software versions 8 & 10

Passport software versions 8 & 10

Indoor EMV OCT 1, 2015

Passport software versions 8 & 10 End of Life June 30, 2017

EMV at Pump OCT 1, 2020

PASSPORT SOFTWARE VERSIONS 8 & 10 END OF LIFE = JUNE 30, 2017

UPGRADE

Indoor Software Upgrade EMV version 11.01

Full Indoor EMV Capabilities

EMV Software Upgrades Requires Technician

NOTE: EMV Acceptance will require upgraded software and EMV capable PINpads

Gilbarco POS INDOOR EMV Roadmap

All-In-One Passports (PX60) using 10.0K

Software version 10.0K

Indoor EMV OCT 1, 2015

Passport software versions 8 & 10 End of Life June 30, 2017

EMV at Pump OCT 1, 2017

PASSPORT SOFTWARE VERSIONS 8 & 10 END OF LIFE = JUNE 30, 2017

UPGRADE

Indoor Software Upgrade EMV version 11.01

Full Indoor EMV Capabilities

EMV Software Upgrade Requires Technician

NOTE: EMV Acceptance will require upgraded software and EMV capable PINpads

Gilbarco POS OUTDOOR EMV Roadmap

INDOOR EMV Software Upgrade
Requires Technician



Indoor AND Outdoor EMV Acceptance will require:

1. Upgraded software
2. EMV capable PIN Pads
3. New Secure Zone Router

OUTDOOR EMV Software Upgrade
Requires Technician +
New Hardware Addition = Secure Zone Router

Gilbarco Passport POS Roadmap

Passport software version 11.01 (CITGO sw v. 007)	• Indoor EMV available now • Software upgrades must be completed before June 30, 2017 • New locations must use software version 11.01
Passport software versions 8 & 10 (CITGO sw v. 001 & 005)	• End of Life June 30, 2017 • **Sites deactivated on June 30, 2017** • Not available for new locations • Does not support MasterCard BIN “2” requirement June 30, 2017 • Does not meet current PCI PA-DSS requirement version (3.2)

Contact Gilbarco:

Bryan Crossan
Director of Sales
Bryan.Crossan@Gilbarco.com
Cell: 336-279-0285

www.gilbarco.com **www.veeder.com**
http://c-storeadvisor.gilbarco.com/

GILBARCO
VEEDER-ROOT